



Loading Manual for TAs




1. Wait for robot to come to a stop, upon detecting the NFC tag.
2. Remove rubber band from funnel mouth.



3. Load the ping pong balls by gently pushing them into the funnel mouth.



4. Twist the rubber band two rounds and reattach it onto the extrusions.



5. Shine the given torchlight on the LDR for 10 seconds to trigger the robot to start moving again.

