

🕒	23 JUL 2021
19:07	Object arrived at Installation
24 JUL 2021	
13:13	Moored Alongside Berth (All Fast)
14:00	Hose / Arm Connected
15:15	Saybolt onboard before Operation
15:20	Commenced Initial Inspection
15:45	Completed Initial Inspection, Tank(s) Inspected and Accepted
16:11	COMMENCED LOADING
21:48	COMPLETED LOADING
22:10	Hose / Arm Disconnected
25 JUL 2021	
06:00	Saybolt onboard after Operation
06:01	Commenced Final Inspection
07:15	Completed Final Inspection and Calculations, Tank(s) Measured and Sampled
12:15	Object Sailed / Departed

Bill of Lading	↕	After Loading
G.S.V. Liters (15°C)	-196	
1 387 717	-0.01%	1 387 521
G.S.V. Barrels (60°F)	-1.26	
8 732	-0.01%	8 730.74
Metric Tons Vac (Vac)	-0.128	
1 197.559	-0.01%	1 197.431
Metric Tons Air (Air)	-0.128	
1 196.074	-0.01%	1 195.946
Density 15°C kg/L (Vac)		
0.8630		0.8630
Date		
24 Jul 2021		25 Jul 2021

Remarks

For questions or remarks please contact:
 Leonie Snoek
 Leonie.Snoek@corelab.com

Issued by: Doni Vargas Reynoso
 Date of issue: 26 jul 2021

Our reference number: 12004/00133470

This copy is provided for courtesy purposes only. No rights exist for any bearer of this document, except for the explicit principal(s) of the referred nomination.

This report reflects the findings at the time of the inspection and has been created with care and professional judgement.