



SEWER LOCATE CARD


Date: 5/9/2018	Pre Video Complete <input checked="" type="checkbox"/>	Post Video Complete <input type="checkbox"/>	Pull Back Camera Only w/ Site Investigation <input type="checkbox"/>
City: Richmond		TCC:	
Street Address: 8130 Canberra Dr.		PSID/Site ID:	
Job Order No. 17-037237-00		Proj ID	
NiSource Representative:		Contractor Name:	
Main Foreman:		Service Foreman:	
Camera Locator Pre: Matt Arnold		Camera Locator Post:	
Camera Operator Pre: James R. Krauz		Camera Operator Post:	

Sanitary on another Locate Card ☒Was sanitary main located? Yes ☒ No ☐ Method used: Push Camera ☐ Tractor Camera ☒Was sanitary lateral located? Yes ☐ No ☐ Method used: Push Camera ☐ Tractor Camera ☐

If no, explain:

Storm on another Locate Card ☐Was storm main located? Yes ☒ No ☐ Method used: Push Camera ☐ Tractor Camera ☒Was storm lateral located? Yes ☐ No ☒ Method used: Push Camera ☐ Tractor Camera ☐

If no, explain: Storm laterals have metal grates in ends.

POINT	MEASUREMENTS		INDICATE NORTH
			
A	36'7" CB2	39'5" FRW	3'4"
B	17'3" CB1	33'6" FRW	3'7"
C	36'5" CB1	24'5" FRW	3'9"
D	7' FCB2	19'5" FRW	3'10"
E	11'9" FCB2	14' FRW	4'
F	33'9" FCB2	4' FRW	4'3"
G	62' FCB2	19'6" FCB3	4'2"
H	40'3" FCB4	43'1" FCB5	5'6"
I	19'9" FCB3	24'5" FRW	4'
J	40'3" FCB3	4'5" FRW	3'9"
K			

SKETCH

Banksstown Ln.

8130

Canberra Dr.

SMH001

CB1, CB2, CB3, CB4, CB5

(A), (B), (C), (D), (E), (F), (G), (H), (I), (J), (K)

Method Main Installed:		Method Service Installed:	
Main Pre Bore Review Walk Performed By:	NiSource Rep:	Foreman:	Bore Lead:
Service Pre Bore Review Walk Performed by:	NiSource Rep:	Foreman:	Bore Lead:

Pull Back Camera Used and Video Verified Clear with Site Investigation Performed - No ☐ Yes ☐ By:

Comments: