

(RE)EVALUATION LEAK WORK ORDER

SECTION 1 - PROJECT DATA					LEAK NUMBER		WORK ORDER #		DUE DATE		
HOUSE		Unit #	STREET		CITY				PLAT MAP		
SECTION 2 - RESPONSE								SECTION 3 - (RE)EVALUATION			
RESPONSE TYPE		GRADE FOUND		INSIDE INVESTIGATION REQUIRED?		INSIDE INVESTIGATION PERFORMED?		GRADE LEFT		BAR TEST TO TIE-IN REQUIRED?	
J		Zero		No		No		Zero		No	
RESPONSE CO.		RESPONDER NAME		EQUIPMENT ID		ARRIVAL DATE		TIME		FINISH DATE	
HYDROMAX USA		Collins Salifu		9101551014		02/23/2019		15:50		02/23/2019	
								UNDERGROUND		BAR TEST TO TIE-IN PERFORMED?	
								Yes		No	
DESCRIPTION AND LOCATION OF REPAIR AND/OR THE LOCATION OF CGIS READS AS LEFT										PSE GAS SYSTEM DISPLAYED ACCURATELY	
										Yes	
<p>located 5ft s c/l 73rd pl w and 10ft e c/l 73rd pl sw. also located 3ft n #7308 s edge of d/w and 62ft nw of nwbl #7308.</p> <p>No Spread</p> <p>Highest Gas Percentage: % Latitude: Longitude:</p>											

