

20. January 2010, [hb9pit@uska.ch](mailto:hb9pit@uska.ch)

## MC-60A RFI Modification

Just switching off the preamp is not a solution when you have RFI problems with that fine Kenwood mic. Then the mic level is too low for VOX operation. But it is so easy to fix the problem. Just open the mic and unscrew the switch at the bottom plate. Then cut the copper foil of the PC switch-board between the switch housing and the black wire. That can be done with a knife. Many hams did that modification with success.

