



WAAS00127466 S15-133 UDREi Bumping


- Timeline:
 - 6/12 - S15-133 started bumping to UDREi 11 for a few hours 2ce/day
 - 6/19 - performed manual switchover in an attempt to mitigate / add new data point
 - 6/23 - after a quiet few days, bumping returned
 - 6/24 - bumping coinciding with SM9 switchover caused LPV200 outage in NW Alaska (both GEOs at 11)
 - 6/29 - started bumping to NM (UDREi 14)
 - 7/6 - jumped briefly to DU



WAAS00127466 S15-133 UDREi Bumping



WAAS00127466 S15-133 UDREi Bumping



WAAS00127466 S15-133 UDREi Bumping

Investigation Ongoing:

- not issuing a NOTAM at this time
- no current plans to cold start the S15-133 GUSs BR1/CM1
- no current plans to perform another non-cutover related switchover
- considering changing the order of the BR1/CM1 upgrades to avoid unnecessary switchovers