

REV 0.3

BUGFIX: LCD RW must be set to GND

BUGFIX: ESP32 cannot supply enough current for Relay, added Q1

Moved RFID card to the right to avoid overlap with DEFAULTS button

Changed large caps to 0805 footprints

Replaced variable resistor with more common footprint

Added components values

Added Input protections with fuses

Changed tactile switches model to through hole model

USB tracks rerouted to avoid pads breaking the data lines

Add large cap for LCD power

Can't move LCD hole out of the terminal blocks

