



Appliance AD Report

VAAV
08:42

10.Mar.2022
Page 1/35

For Aircraft `VQ-BTC` (S/N: 43662, Act.TAH: 31435, Act.TAC: 14264)

Selection: AIRWORTHINESS DIRECTIVE

Document-Number	Type	Rev	Compliance	A C	Subject	Status
1998-162	AD	R01	Mandatory	COMP	INSPECTION OF HYDROMECHANICAL UNIT OVER SPEED GOVERNOR SPOOL VALVES	Not Applicable
Complete document sign-up hierarchy						
1998-162/AD Rev.R01					INSPECTION OF HYDROMECHANICAL UNIT OVER SPEED GOVERNOR SPOOL VALVES	Not Applicable
> CFM56-7B-73-0016/SB* Rev.R02					HMU SCHEDULED INSPECTION	Not Applicable by Component Serial Number
					Affected Rotables (Part No / Serial No / Position)	Status / Next Due / Time Req. / W/O
					CFM56-7B24E / 660409 Pos=RHENG (VQ-BTC)	Not Applicable / Reason: AUTO ASSIGNED
					CFM56-7B24E / 660391 Pos=LHENG (VQ-BTC)	Not Applicable / Reason: AUTO ASSIGNED
1998-259	AD	R01	Mandatory	COMP	TO PREVENT AN UNCOMMANDED DUAL INFLIGHT ENGINE SHUTDOWN	Not Applicable by Component Serial Number
					Affected Rotables (Part No / Serial No / Position)	Status / Next Due / Time Req. / W/O
					CFM56-7B24E / 660391 Pos=LHENG (VQ-BTC)	Not Applicable / Reason: AUTO ASSIGNED
					CFM56-7B24E / 660409 Pos=RHENG (VQ-BTC)	Not Applicable / Reason: AUTO ASSIGNED
1998-350	AD	R02	Mandatory	COMP	UNCOMMANDED ENGINE ACCELERATION EVENT OR IN FLIGHT ENGINE SHUTDOWN	Not Applicable
Complete document sign-up hierarchy						
1998-350/AD Rev.R02					UNCOMMANDED ENGINE ACCELERATION EVENT OR IN FLIGHT ENGINE SHUTDOWN	Not Applicable
> CFM56-7B-73-A0024/SB* Rev.R0					EEC-SOFTWARE VER. 7.B.I1 (7B38)	Not Applicable by Component Serial Number
					Affected Rotables (Part No / Serial No / Position)	Status / Next Due / Time Req. / W/O
					CFM56-7B24E / 660409 Pos=RHENG (VQ-BTC)	Not Applicable / Reason: AUTO ASSIGNED
					CFM56-7B24E / 660391 Pos=LHENG (VQ-BTC)	Not Applicable / Reason: AUTO ASSIGNED
2001-02-12	AD	R0	Mandatory	COMP	AIR LEAKAGE FROM INCORRECTLY TORQUED FITTINGS OF THE PS3 PRESSURE LINE	Not Applicable