

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.249
2AEFO-GZFUSION1
15-0106
April 14, 2015
Gozio, Inc.
FUSION Beacon 1.0

EXTERNAL PHOTOGRAPHS



Figure 1. Top of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.249
2AEFO-GZFUSION1
15-0106
April 14, 2015
Gozio, Inc.
FUSION Beacon 1.0



Figure 2. Bottom of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.249
2AEFO-GZFUSION1
15-0106
April 14, 2015
Gozio, Inc.
FUSION Beacon 1.0




Figure 3. Bottom of EUT with Battery Compartment Showing

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.249
2AEFO-GZFUSION1
15-0106
April 14, 2015
Gozio, Inc.
FUSION Beacon 1.0



Figure 4. Left Side of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.249
2AEFO-GZFUSION1
15-0106
April 14, 2015
Gozio, Inc.
FUSION Beacon 1.0



Figure 5. Right Side of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.249
2AEFO-GZFUSION1
15-0106
April 14, 2015
Gozio, Inc.
FUSION Beacon 1.0



Figure 6. Front of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.249
2AEFO-GZFUSION1
15-0106
April 14, 2015
Gozio, Inc.
FUSION Beacon 1.0



Figure 7. Back of EUT