

Cover letter

Date: 2/8/2018

FCC ID: VW3FAST5260CV


Federal Communication Commission
445 12th Street, SW
Washington, DC 20554

To whom it may concern:

This attestation is provided to explain the error of note code 38 for Sagemcom Broadband SAS grants under FCC ID: VW3FAST5260CV.

The error was introduced for the following grants.

1. Grant issued on 2/4/2016, TC850761. This was a Class II Permissive change application to introduce two AC/DC power supplies. So all the note codes from previous grant should have been the same. Only 5150-5240MHz band should have note code 39. Instead note code 39 was added for all the bands for UNII grant. This appears to have been a simple administrative error.
2. Next grant was issued on 5/18/2016, TC508829. This was a Class II Permissive change application to update UNII Band 3 (5745-5825MHz) previously authorized under 15.247 to be modified to operate under the New rules and the technical requirements of 15.407 (b) (4) (ii) with no changes in total power or hardware changes. So this grant should have note code 39 for 5150-5240MHz from previous grants and note code 49 for 5745-5825MHz band. Instead note code 38 was added to all the bands for UNII grant.
3. Next grant was issued on 12/28/2016, TC383125. This was a Class II Permissive change application to introduce additional AC/DC power supply. So this grant should have note code 39 for 5150-5240MHz and note code 49 for 5745-5825MHz band from previous grants. Instead the error of note code 38 was carried forward and note code 38 was added to all the bands for UNII grant. Also, note code ND for DFS bands on NII grant for this application is an error since DFS bands were not tested to new requirements of Docket 13-49.



Scott Lambert
Certification Manager
Curtis-Straus