

Prüfbericht - Nr.: 12603897 004
Test Report No.:

Seite 42 von 46
Page 42 of 46

8. Photographs of test setup

Photograph 1: Set-up for Conducted Testing




Prüfbericht - Nr.: 12603897 004
Test Report No.:

Seite 43 von 46
Page 43 of 46

Photograph 2: Set-up for Radiated Emission, EUT Configuration X-axis




Photograph 3: Set-up for Radiated Emission, EUT Configuration Y-axis



Prüfbericht - Nr.: 12603897 004
Test Report No.:

Seite 44 von 46
Page 44 of 46

Photograph 4: Set-up for Radiated Emission, EUT Configuration Z-axis



Photograph 5: Set-up for Radiated Emission

