

Prüfbericht - Nr.: 12606813 001
*Test Report No.:***Seite 46 von 54**
Page 46 of 54


8. Photographs of the Test Setup


Photograph 1: Set-up for Conducted Emissions at Antenna Port



Prüfbericht - Nr.: 12606813 001
*Test Report No.:*Seite 47 von 54
Page 47 of 54**Photograph 2: Set-up for AC Power Line Conducted Emission of Transmitter, Front View****Photograph 3: Set-up for AC Power Line Conducted Emission of Transmitter, Rear View**

Prüfbericht - Nr.: 12606813 001
*Test Report No.:***Seite 48 von 54**
*Page 48 of 54***Photograph 4: Set-up for AC Power Line Conducted Emission of Receiver, Front View****Photograph 5: Set-up for AC Power Line Conducted Emission of Receiver, Rear View**

Prüfbericht - Nr.: 12606813 001
*Test Report No.:***Seite 49 von 54**
*Page 49 of 54***Photograph 6: Set-up for Radiated Emission of Transmitter, Front View****Photograph 7: Set-up for Radiated Emission of Transmitter, Rear View**

Prüfbericht - Nr.: 12606813 001
*Test Report No.:***Seite 50 von 54**
*Page 50 of 54***Photograph 8: Set-up for Radiated Emission of Receiver, Front View****Photograph 9: Set-up for Radiated Emission of Receiver, Rear View**

Prüfbericht - Nr.: 12606813 001
*Test Report No.:*Seite 51 von 54
Page 51 of 54**Photograph 10: Set-up for Radiated Emission, EUT Configuration X-Axis****Photograph 11: Set-up for Radiated Emission, EUT Configuration Y-Axis**

Prüfbericht - Nr.: 12606813 001
Test Report No.:

Seite 52 von 54
Page 52 of 54

Photograph 12: Set-up for Radiated Emission, EUT Configuration Z-Axis

