

# Statement

Date: July 05, 2013

FCC ID: XBI9821036

Product Name: MID

Model Name: ID982WTA, NC820, NC830, NC850, NC860, NC870, NC900, NC700, NC810, NC822, NC833, NC852, NC862, NC880, NC910, NC710, NC812, NC823, NC836, NC856, NC863, NC828, NC868, NC816, NC813, NC826, NC838, NC858, NC866, NC818, ID800WTA, ID812WTA, ID822WTA, ID830WTA, ID860WTA, ID870WTA, ID880WTA, ID890WTA, ID802WTA, ID816WTA, ID826WTA, ID836WTA, ID866WTA, ID809WTA, ID819WTA, ID803WTA, ID818WTA, ID828WTA, ID838WTA, ID868WTA, ID808WTA, ID806WTA, ID900WTA, ID910WTA, ID920WTA, ID930WTA, ID970WTA, ID980WTA, ID979WTA, ID988WTA, ID902WTA, ID912WTA, ID922WTA, ID933WTA, ID971WTA, ID981WTA, ID978WTA, ID975WTA, ID903WTA, ID913WTA, ID917WTA, ID936WTA, ID972WTA, ID977WTA, ID908WTA, ID905WTA, ID915WTA, ID906WTA, ID976WTA, ID973WTA, ID986WTA, ID907WTA, ID732WTA, ID750WTA, ID722WTA, ID780WTA, ID790WTA, ID798WTA, ID756WTA, ID738WTA, ID753WTA, ID773WTA, ID782WTA, ID792WTA, ID795WTA, ID778WTA, ID788WTA, ID736WTA, ID755WTA, ID776WTA, ID783WTA, ID793WTA, ID796WTA, ID786WTA, ID1036WTA, ID1050WTA, ID1060WTA, ID1070WTA, ID1077WTA, ID1073WTA, ID1063WTA, ID1058WTA, ID1039WTA, ID1053WTA, ID1062WTA, ID1072WTA, ID1067WTA, ID1057WTA, ID435WTA, ID4320WTA, ID4330WTA, ID4336WTA, ID4360WTA, ID4322WTA, ID4321WTA, ID4331WTA, ID4338WTA, ID4366WTA, ID437WTA, ID1100WTA, ID1106WTA, ID1102WTA, ID1105WTA, ID1101WTA, ID1300WTA, ID1301WTA, ID1302WTA, ID1305WTA, ID1308WTA, STB372, STB500, STB600, STB623, STB630, STB375, STB510, STB602, STB625, STB633, STB378, STB512, STB607, STB627, STB637, STB638, STB517, STB608, STB628, STB636, AD1500

We

SUNGALE ELECTRONICS (SHENZHEN) CO., LTD

Hereby that

The product MID with has employed the RF Modular with model name RL-UM02BS-RTL8723VAU. The RF chip is RTL8723AS-VAU. The modular has WIFI and Bluetooth function. But in the product, the Bluetooth function is permanently disabled by software

Your assistance on this matter is highly appreciated.

Yours sincerely,

Signature: 

Company Name: SUNGALE ELECTRONICS (SHENZHEN) CO., LTD