

**Configuration Photographs**

**Worst-Case Line-Conducted Emissions**

**(Front View)**

**Model : TRFM915**

**External Antenna**




**Configuration Photographs**

**Worst-Case Line-Conducted Emissions**

**(Back View)**

**Model : TRFM915**

**External Antenna**




**Configuration Photographs**

**Worst-Case Line-Conducted Emissions**

**(Side View)**

**Model : TRFM915**

**External Antenna**



# **INTERTEK TESTING SERVICE**

---

Report No: HK11040905-2

## **Configuration Photographs**

### **Worst-Case Line-Conducted Emissions**

**(Front View)**

**Model : TRFM915**

**Trace Antenna**



---

## INTERTEK TESTING SERVICE

---

Report No: HK11040905-2


### Configuration Photographs

#### Worst-Case Line-Conducted Emissions

(Back View)

Model : TRFM915

Trace Antenna



**Configuration Photographs**

**Worst-Case Line-Conducted Emissions**

**(Side View)**

**Model : TRFM915**

**Trace Antenna**

