

FamilyMart

Pest Inspection Report

Post-Inspection Report / MFM0131 Porto Historia / 18 Jul 2025

Complete

Inspection	Post-Inspection Report
Store ID and Name	MFM0131 Porto Historia
Tracker	Other pest
Inspector	Irshad
Project Team PIC	Faiz
Project Team Present	Yes
Contractor Present	No
Inspection Date	18.07.2025
Report Date	18.07.2025
Handover Date	18.07.2025

Findings

Findings #1

LocationSales Floor - Counter Cabinet

Observations



Photo 1



Photo 2



Photo 3

FindingsNoted with a hole.

RecommendationKindly assist to seal.

StatusNew Findings

Findings #2

LocationKitchen Area - Underneath Counter Cabinet

Observations



Photo 4




Photo 5



Photo 6

FindingsNoted with gaps.

RecommendationKindly assist to seal.

StatusNew Findings

Findings #3

LocationKitchen Area - Underneath Counter Cabinet

Observations



Photo 7



Photo 8

Findings

Noted with a gap.

Recommendation

Kindly assist to seal.

Status

New Findings

Findings #4

Location

Kitchen Area - Ventilation Hood

Observations




Photo 9



Photo 10

Findings

Noted with cracks.

Recommendation

Kindly assist to seal.

Status

New Findings

Findings #5

Location

Kitchen Area - Wall

Observations



Photo 11



Photo 12

Findings

With with a gap.

Recommendation

Kindly assist to seal.

Status

New Findings

Findings #6

Location Kitchen Area - Counter Cabinet

Observations




Photo 13



Photo 14



Photo 15

Findings Wiring connected through the wall with gaps.

Recommendation Kindly assist to seal.

Status New Findings

Findings #7

Location Kitchen Area - Counter Cabinet

Observations



Photo 16



Photo 17



Photo 18



Photo 19

Findings Noted with gaps.

Recommendation Kindly assist to seal.

Status New Findings

Findings #8

Location Sales Floor - Store Room

Observations




Photo 20



Photo 21



Photo 22



Photo 23



Photo 24




Photo 25

Findings	Noted with cracks and a gap.
Recommendation	Kindly assist to seal.
Status	New Findings
Findings #9	

Location	Kitchen Area - Floor Trap
----------	---------------------------

Observations



Photo 26



Photo 27

Findings	There is no metal wire mesh net installed.
Recommendation	Kindly assist to install the metal net.
Status	New Findings
Findings #10	

Location	Backroom - Staff Toilet
----------	-------------------------

Observations



Photo 28



Photo 29



Photo 30




Photo 31



Photo 32




Photo 33



Photo 34




Photo 35



Photo 36



Photo 37

Findings	Noted with cracks and gaps.
Recommendation	Kindly assist to seal.
Status	New Findings

Findings #11

LocationBackroom - Backdoor (Right side)

Observations



Photo 38




Photo 39



Photo 40




Photo 41



Photo 42

FindingsNoted external light which indicatong gaps.

RecommendationKindly assist to install bristle strips.

StatusNew Findings

Findings #12

LocationBackroom - Reach-In Freezer

Observations



Photo 43




Photo 44

FindingsFloor base with cracks.

RecommendationKindly assist to seal.

StatusNew Findings

Findings #13

LocationBackroom - Ceiling

Observations



Photo 45




Photo 46

Findings

Copper piping connected through ceiling with a gap.

Recommendation

Kindly assist to seal.

Status


New Findings

Findings #14

Location

Backroom - Floor Skirting

Observations



Findings

Noted with a gap.

Recommendation

Kindly assist to seal.

Status


New Findings

Findings #15

Location

Backroom - Backdoor (Left Side)

Observations



Findings

Noted with gaps.

Recommendation

Kindly assist to install with bristle strips.

Status

New Findings

Findings #16

Location

Backroom - Wiring

Observations



Photo 56



Photo 57



Photo 58



Photo 59




Photo 60



Photo 61



Photo 62




Photo 63



Photo 64



Photo 65



Photo 66

Findings

Noted with gaps.

Recommendation

Kindly assist to seal.

Status

New Findings

Findings #17

Location

Backroom - Septic Tank

Observations



Photo 67



Photo 68



Photo 69




Photo 70



Photo 71

Findings

Noted with damaged proofing.

Recommendation

Kindly assist to seal.

Status

New Findings

Findings #18

Location

Backroom - Above Ceiling

Observations



Photo 72




Photo 73




Photo 74

Findings Noted with gaps.

Recommendation Kindly assist to seal.

Status New Findings

Findings #19

Location Backroom - Server Box

Observations




Photo 75



Photo 76



Photo 77



Photo 78

Findings Wiring connected through the ceiling with a gap.

Recommendation Kindly assist to seal.

Status New Findings

Findings #20

Location Dining Area - Floor Skirting

Observations



Photo 79




Photo 80




Photo 81

Findings Noted detached.

Recommendation Kindly assist to rectify.

Status New Findings

Findings #21

Location Sales Floor - Store Room

Observations



Photo 82



Photo 83




Photo 84

Findings Noted with a gap.

Recommendation Kindly assist to seal.

Status New Findings

Findings #22

Location Sales Floor - Light Beading

Observations



Photo 85




Photo 86

Findings Wiring connected through wall with a gap.

Recommendation Kindly assist to seal.

Status New Findings

Findings #23

Location Sales Floor - Customer Toilet

Observations



Photo 87



Photo 88



Photo 89



Photo 90



Photo 91

Findings	Ceiling skirting with gaps.
Recommendation	Kindly assist to seal.
Status	New Findings
Findings #24	
Location	Backroom - Backdoor

Observations



Photo 92



Photo 93

Findings	Noted chipped.
Recommendation	Kindly assist to patch up.
Status	New Findings
Findings #25	
Location	External Area - Wall

Observations



Photo 94



Photo 95

Findings	Noted with a hole.
Recommendation	Kindly assist to seal.
Status	New Findings
Findings #26	
Location	Sales Floor - Main Entrance

Observations



Photo 96



Photo 97




Photo 98



Photo 99




Photo 100

Findings	Noted with gaps.
Recommendation	Kindly assist to seal.
Status	New Findings

Media summary



Photo 1



Photo 2



Photo 3



Photo 4




Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12




Photo 13



Photo 14




Photo 15



Photo 16



Photo 17



Photo 18



Photo 19




Photo 20




Photo 21



Photo 22



Photo 23




Photo 24




Photo 25



Photo 26



Photo 27



Photo 28




Photo 29



Photo 30



Photo 31



Photo 32




Photo 33



Photo 34




Photo 35



Photo 36



Photo 37



Photo 38



Photo 39




Photo 40



Photo 41



Photo 42



Photo 43



Photo 44




Photo 45




Photo 46




Photo 47



Photo 48




Photo 49




Photo 50



Photo 51



Photo 52




Photo 53



Photo 54




Photo 55




Photo 56



Photo 57



Photo 58



Photo 59




Photo 60



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65



Photo 66



Photo 67



Photo 68



Photo 69




Photo 70



Photo 71



Photo 72




Photo 73




Photo 74




Photo 75



Photo 76



Photo 77



Photo 78



Photo 79




Photo 80




Photo 81



Photo 82



Photo 83




Photo 84




Photo 85




Photo 86




Photo 87




Photo 88




Photo 89



Photo 90




Photo 91



Photo 92



Photo 93



Photo 94



Photo 95



Photo 96



Photo 97



Photo 99




Photo 98




Photo 100