

## Summary Report with Notes

**Project Name :** Test Project

**Date :** 20/10/2015

**Inspections :** 4

**Page :** 1 of 1

**Report Filtered by :**

**Issue To:**

Wiseworking

| ID                     | Location                           | Description                         | Notes | Inspected By | Date Raised | Raised By | Issued To                  | Fix By Date | Status | Image 1                                                                               | Image 2 | Drawing | Sign Off |
|------------------------|------------------------------------|-------------------------------------|-------|--------------|-------------|-----------|----------------------------|-------------|--------|---------------------------------------------------------------------------------------|---------|---------|----------|
| 109914<br>452210<br>04 | Level 1 ><br>Apt101 ><br>Bedroom 1 | Testing subcontractor defect report |       | kreed        | 19/10/15    | Builder   | Wiseworking (Cathy Jansen) | 23/10/15    | Open   |    |         |         |          |
| 109914<br>452210<br>59 | Level 1 ><br>Apt101 ><br>Bedroom 1 | Paint work needs to be done         |       | kreed        | 19/10/15    | Builder   | Wiseworking (Cathy Jansen) | 23/10/15    | Open   |    |         |         |          |
| 109914<br>452211<br>27 | Level 1 ><br>Apt101 ><br>Bedroom 1 | Hinge on front door is broken       |       | kreed        | 19/10/15    | Builder   | Wiseworking (Cathy Jansen) | 23/11/15    | Open   |  |         |         |          |
| 109914<br>452957<br>76 | Level 1 ><br>Apt101 ><br>Bedroom 1 | Test email                          |       | kreed        | 20/10/15    | Builder   | Wiseworking (Cathy Jansen) | 23/10/15    | Open   |                                                                                       |         |         |          |