



FYI
Technical Bulletin 100-01 / 20 May 1983
Replace R91, R94, and R99 with 330 Ohm to correct issues with RS232.

Transcript of original TRS-80 Model 100 Schematic

Please file mistakes at
<https://github.com/hzeller/trs80-100-schematic> (Henner Zeller; h.zeller@acm.org)
Kyocera / Tandy

Sheet: /
File: trs80-100.kicad_sch
Title: TRS-80 Model 100 Schematic

Size: A2 Date: 1983
KiCad E.D.A. kicad 7.0.9
Rev: 1/1