



I will provide additional information if required.

1. Vehicle Details

- Vehicle Color: Green
- Vehicle Description: Partially visible from the side angle
- License Plate: Not detected
- No additional vehicle data found

2. Initial Assessment

The vehicle was partially visible from the side angle, and an initial assessment was conducted based on the provided information.

3. Damage Details

- Dent detected on the left side of the vehicle (Confidence: 0.83)
- No other damage was observed

4. Repair Recommendations


- Further inspection is required to assess the extent of the damage
- It is recommended to inspect the vehicle's body panels and frame for any additional damage
- A detailed repair estimate should be provided once the assessment is complete

5. Severity Level (Scale 1-5)

- Severity level: 3 (Moderate)

6. Towing Requirements

- The vehicle should be towed to a secure location for further inspection and assessment
- It is recommended to use a flatbed tow truck to prevent further damage to the vehicle



e

- A thorough examination of the vehicle's underside and frame should be conducted during the towing process

The report has been completed. I will wait for your feedback.

I have some additional information regarding the vehicle. The vehicle was involved in an accident with another vehicle and was driven to the location where it was inspected. The driver of the vehicle reported that the vehicle was struck on the left side by another vehicle.

1. Vehicle Details

- Vehicle Color: Green
- Vehicle Description: Partially visible from the side angle
- License Plate: Not detected
- No additional vehicle data found

2. Initial Assessment

The vehicle was partially visible from the side angle, and an initial assessment was conducted based on the provided information.

3. Damage Details

- Dent detected on the