

Deductions

-5	The first entry in the schematic errata document should read pin 23. (T2 had this error.)
-2.5	The build-and-test procedure document should be in place with each tasks documents*
-5	App code wasn't commented very thoroughly, commented fragments remaining, etc.

Reasoning**Comments**

* - Even if no new hardware has been added, the documentation in its entirety should be together in one place for each milestone.