


# Wire your force sensor to the Trinket like so...



The resistor for the force sensor is brown-black-orange-gold (10kohm)

Don't forget how the breadboard is connected...  
(is it vertical or horizontal?)