

Connections from the Weather Click to the PIC32MX curiosity board for SPI operation.
You need to change the 0 Ω resistors to the SPI setting on the click board.

Notes	Pin		
	NC	1	AN
	NC	2	RST
Chip select	CS	3	CS
SPI clock	SCK	4	SCK
SPI Master Input Slave Output	MISO	5	MISO
SPI Master Output Slave Input	MOSI	6	MOSI
Power supply	+3.3V	7	3.3V
Ground	GND	8	GND


The Mikro Weather Click

D4

D2

D3

D5



The PIC32MX Curiosity board