

Module 7. An Introduction to Powder Metallurgy




Extracted from: https://www.youtube.com/watch?v=l39m28NZ7_s

Extracted from: <https://www.youtube.com/watch?v=q7fE343QYP4>

WHAT MANUFACTURING OPTIONS DO WE HAVE TO MAKE A SELF²
LUBRICATED BEARING FOR THESE HIGH-SPEED SPINNING DISKS IN A
CHEMICAL REACTOR?



WHAT MANUFACTURING OPTIONS DO WE HAVE TO MAKE A SELF³ LUBRICATED BEARING FOR THESE HIGH-SPEED SPINNING DISKS IN A CHEMICAL REACTOR?



Self Lubricant Material, Porous Oil-Impregnated Bronze
(Bearing Pad for High Speed Rotating Disks)

WHAT MANUFACTURING OPTIONS DO WE HAVE TO MAKE THIS?

4



A Complex Part in a Spherical Parallel Robot

EXAMPLE OF PM PARTS

5



Car Connecting Rod



Parts in Automotive Carrier System,
and Clutches

Extracted from: <https://www.youtube.com/watch?v=q7fE343QYP4>

EXAMPLE OF PM PARTS

6



Stator Core for Electric Motors,
Made from soft magnetic composite,
and Iron



Rotor core for hybrid electric motors,
Made from Copper steel

Extracted from: <https://www.youtube.com/watch?v=q7fE343QYP4>

PM PARTS EVERY WHERE

7



Extracted from: <https://www.youtube.com/watch?v=q7fE343QYP4>



WHY PM?

- Zero waste

WHY PM?

- Zero waste
- Produced to net shape, eliminating the need for post processing



WHY PM?

- Zero waste
- Produced to net shape, eliminating the need for post processing
- Production of porous metal parts, such as oil-impregnated bearing and self lubricated gears



WHY PM?

- Zero waste
- Produced to net shape, eliminating the need for post processing
- Production of porous metal parts, such as oil-impregnated bearing and self lubricated gears
- Making parts with certain metals such as Tungsten (difficult to fabricate by other methods)



WHY PM?

- Zero waste
- Produced to net shape, eliminating the need for post processing
- Production of porous metal parts, such as oil-impregnated bearing and self lubricated gears
- Making parts with certain metals such as Tungsten (difficult to fabricate by other methods)
- Metal alloy combinations can be formed



WHY PM?

- Zero waste
- Produced to net shape, eliminating the need for post processing
- Production of porous metal parts, such as oil-impregnated bearing and self lubricated gears
- Making parts with certain metals such as Tungsten (difficult to fabricate by other methods)
- Metal alloy combinations can be formed
- Dimensional accuracy with tolerance $\pm 0.1mm$ can be achieved.



WHY PM?

- Zero waste
- Produced to net shape, eliminating the need for post processing
- Production of porous metal parts, such as oil-impregnated bearing and self lubricated gears
- Making parts with certain metals such as Tungsten (difficult to fabricate by other methods)
- Metal alloy combinations can be formed
- Dimensional accuracy with tolerance $\pm 0.1mm$ can be achieved.
- PM process can be automated.



PRODUCTION OF METALLIC POWDER

15




Image Source: <http://www.mt-innov.com/index.php?ac=article&at=list&tid=12>

PRODUCTION OF METALLIC POWDER

16




Image Source: <http://www.mt-innov.com/index.php?ac=article&at=list&tid=12>


THE SEQUENCE OF PM PROCESS

- Blending or Mixing
- Add lubricant (oil)
- Pressing
- Sintering



THE SEQUENCE OF PM PROCESS

- Blending or Mixing
- Add lubricant (oil)
- Pressing
- Sintering




Extracted from: <https://www.youtube.com/watch?v=O7U4HWjYcgo>



THE SEQUENCE OF PM PROCESS

- Blending or Mixing
- Add lubricant (oil)
- Pressing
- Sintering




Required Pressure:

- Ferrous Powder: 400-700 MPa
- Aluminium alloy Powder: 100-400 MPa
- Copper and Bronze alloy : 400 MPa



THE SEQUENCE OF PM PROCESS


- Blending or Mixing
- Add lubricant (oil)
- Pressing
- Sintering



Extracted from: <https://www.youtube.com/watch?v=O7U4HWjYcgo>



THE SEQUENCE OF PM PROCESS

- Blending or Mixing
- Add lubricant (oil)
- Pressing
- Sintering



THE SEQUENCE OF PM PROCESS

- Blending or Mixing
- Add lubricant (oil)
- Pressing
- Sintering



Extracted from: <https://www.youtube.com/watch?v=PetwxkqM-kQ>

SECONDARY OPERATIONS

1. Machining

For geometrical features that cannot be achieved by pressing, like threads, side holes



SECONDARY OPERATIONS

2. Oil Impregnation

For self-lubricated bearing or gears, usually Bronze or Iron about 10% volume oil, by immersing the sintered parts in a bath of hot oil.



SECONDARY OPERATIONS

3. Infiltration



SECONDARY OPERATIONS

3. Infiltration

- **By Polymer**

For pressure tight parts, Liquid Polymer seep into the pore spaces and then solidify.



SECONDARY OPERATIONS

3. Infiltration

- **By Polymer**

For pressure tight parts, Liquid Polymer seep into the pore spaces and then solidify.



- **By Other Metal**

For improve toughness, strength or other physical properties, The pores of PM part are filled with a molten metal, the melting point of filler must be below that of the PM part




DESIGN CONSIDERATION

Part Features to avoid:




DESIGN CONSIDERATION

Part Features to avoid:




DESIGN CONSIDERATION


Part Features to avoid:



Recommended



DESIGN CONSIDERATION



Recommended Wall thickness > 1.5 mm