

Corrosion Inspection Report

Image: img12_jpg.rf.dc930f9232a7310521fc6c7648c219a0.jpg

Generated on: report_104.pdf

Detection Result:

(1 spot(s))

High=1, Medium=0, Low=0

