

Corrosion Inspection Report

Report: bolt inspection 24.08.2025

Image: marked_result_251e6916.jpg

Generated on: report_123.pdf

Corrosion Detected: PASS (2 spot(s))

Severity: High=1, Medium=1, Low=0

Comments & Observations:

pipe

