

Corrosion Inspection Report

Image: img12_jpg.rf.d66cb1ddd828dc75d6e7119890ac9186.jpg


Generated on: report_15.pdf

Results

Corrosion Detected: PASS (1 spot(s))

Severity: High=0, Medium=0, Low=1

Original Image



Detected Corrosion

