

# CorrosionGuard AI

## Corrosion Inspection Report

Image: img61\_jpg.rf.3667f0e26a65e2eea99049744b6601aa.jpg

Time: 2025-08-23 09:56:20 (MYT)

### Inspection Summary


Corrosion Detected: PASS (5 spot(s))

Severity: High=1, Medium=0, Low=4

Original Image



Detected Corrosion



Generated by CorrosionGuard AI

AI-generated report for analysis only