

Corrosion Inspection Report

Image: img0_jpg.rf.b5bc55cb84018cc1e4bb86eb71e00284.jpg

Generated on: report_17.pdf

Results

Corrosion Detected: PASS (5 spot(s))

Severity: High=1, Medium=1, Low=3

Original Image



Detected Corrosion

segmentation 0.65

segmentation 0.56

