

Corrosion Inspection Report

Image: pipes-metal-2022-12-15-22-16-59-utc.jpg

Generated on: report_98.pdf


Detection Result:

(10 spot(s))

High=4, Medium=0, Low=6



Original Image



Detected Corrosion