

Corrosion Inspection Report

Report: dfgffgh

Image: pipes-metal-2022-12-15-22-16-59-utc.jpg

Generated on: report_107.pdf

Corrosion Detected: PASS (10 spot(s))


Severity: High=4, Medium=0, Low=6

Comments & Observations:

gfhfghfh



Original Image



Detected Corrosion