

Corrosion Inspection Report

Image: img95_jpg.rf.b1930314743fd9c9592ba09bbb83541c.jpg

Generated on: test1_87.pdf

Detection Result:

(5 spot(s))

High=2, Medium=0, Low=3

Comments & Observations:

[Markup saved]

