

# Corrosion Inspection Report

Image: img187\_jpg.rf.8270fdbd03cbb3bb6941d20883d4f17d.jpg

Generated on: report\_28.pdf

## Results

Corrosion Detected: PASS (1 spot(s))

Severity: High=1, Medium=0, Low=0

## Original Image



Detected Corrosion

