

Corrosion Inspection Report

Report: pipes-metal-2022-12-15-22-16-59-utc.jpg

Image: pipes-metal-2022-12-15-22-16-59-utc.jpg


Generated on: report_105.pdf

Corrosion Detected: PASS (10 spot(s))

Severity: High=4, Medium=0, Low=6



Original Image



Detected Corrosion