

Corrosion Inspection Report

Image: img12_jpg.rf.d66cb1ddd828dc75d6e7119890ac9186.jpg

Generated on: report_82.pdf

Detection Result:

(1 spot(s))

High=1, Medium=0, Low=0

Comments & Observations:

[Markup saved]

Marked-up Image

