

Corrosion Inspection Report

Image: img1_jpg.rf.5595321f0a8a5dfb6714400d5864b8ce.jpg

Generated on: report_85.pdf

Detection Result:

(4 spot(s))

High=1, Medium=0, Low=3

Comments & Observations:

severely

Marked-up Image

