

# Corrosion Inspection Report

Image: img106\_jpg.rf.1f433f29ce3f2f70454fb4d9c1708bc9.jpg

Generated on: report\_116.pdf

## Detection Result:

(2 spot(s))

High=2, Medium=0, Low=0

