

# Corrosion Inspection Report

Image: img61\_jpg.rf.ef7876eb87333d022bbbcf22ae5bc4e6.jpg


Generated on: report\_16.pdf

## Results

Corrosion Detected: PASS (1 spot(s))

Severity: High=0, Medium=0, Low=1

## Original Image



Detected Corrosion

