

# CorrosionGuard AI

## Corrosion Inspection Report

Inspected Image: img129\_jpg.rf.81be984d7c0b757148478147a260ee4c.jpg

Generated on: 2025-08-22 22:28:57 (MYT)

### Inspection Summary


Corrosion Detected: PASS (6 spot(s))

Severity: High=1, Medium=1, Low=4

### Original Image



**Detected Corrosion**



Generated by CorrosionGuard AI AI System  
This report is AI-assisted. Final judgment should include human verification.