

# Corrosion Inspection Report

Image: img106\_jpg.rf.bef9029ceab165faa588c1993c1e25af.jpg

Generated on: report\_24.pdf

## Results

Corrosion Detected: PASS (3 spot(s))

Severity: High=3, Medium=0, Low=0

## Original Image



Detected Corrosion

