

Corrosion Inspection Report

Image: img86_jpg.rf.28a592268618f80aaf0755f6d7af1550.jpg

Generated on: report_83.pdf

Detection Result:

(8 spot(s))

High=2, Medium=0, Low=6

Comments & Observations:

test

Marked-up Image

