

Corrosion Inspection Report

Image: img0_jpg.rf.926a5df791764df3d1c28ae7e76c0b3c.jpg

Generated on: report_98.pdf

Detection Result:

(10 spot(s))

High=2, Medium=1, Low=7

