

Corrosion Inspection Report

Image: img131_jpg.rf.0a38ff0cf1f908a7b26610d93a4596b2.jpg

Generated on: report_81.pdf


Detection Result:

(7 spot(s))

High=3, Medium=1, Low=3



Original Image



Detected Corrosion