

Corrosion Inspection Report

Image: mobile_6fdae2c0.jpg

Generated on: report_97.pdf

Detection Result:

(1 spot(s))

High=1, Medium=0, Low=0

Original image missing	Detected image missing
------------------------	------------------------

Original Image

Detected Corrosion