

Corrosion Inspection Report

Image: img90_jpg.rf.af7268b2f45e41750f2693699bb0decd.jpg

Generated on: report_96.pdf

Detection Result:

(4 spot(s))

High=4, Medium=0, Low=0

