

Corrosion Inspection Report

Image: img122_jpg.rf.9560046bbe77d2e3f94008bc2d30470f.jpg

Generated on: report_99.pdf

Detection Result:

(1 spot(s))

High=1, Medium=0, Low=0



Original Image



Detected + Masking