

Corrosion Inspection Report

Image: img138_jpg.rf.5927d6bef02fe2b8ca547e37c6b18264.jpg

Generated on: report_88.pdf

Detection Result:

(8 spot(s))

High=1, Medium=1, Low=6

Comments & Observations:

look good

