

Corrosion Inspection Report

Image: img111_jpg.rf.73ae7e8bc747296dfa23451c128ab86c.jpg

Generated on: report_22.pdf

Results

Corrosion Detected: PASS (1 spot(s))

Severity: High=1, Medium=0, Low=0

Original Image



Detected Corrosion

