

Corrosion Inspection Report

Image: img0_jpg.rf.16fe45e444488606e751c13c499b90d0.jpg

Generated on: report_101.pdf

Detection Result:

(13 spot(s))

High=1, Medium=0, Low=12

