

# Corrosion Inspection Report

Image: img1\_jpg.rf.5595321f0a8a5dfb6714400d5864b8ce.jpg

Generated on: report\_108.pdf

## Detection Result:

(4 spot(s))

High=1, Medium=0, Low=3

