

Corrosion Inspection Report

Report: bolt inspection 24.08.2025

Image: marked_result_bc134143.jpg

Generated on: report_126.pdf

Corrosion Detected: PASS (2 spot(s))

Severity: High=2, Medium=0, Low=0

Comments & Observations:

igj

