

# Corrosion Inspection Report

Image: pipes-metal-2022-12-15-22-16-59-utc.jpg

Generated on: report\_104.pdf

## Detection Result:

(10 spot(s))

Severity: High=4, Medium=0, Low=6

## Comments & Observations:

hfgfhgh

*Error embedding images.*